


FACILITY	DATE
Sample Building	17/03/2004

Location: 2nd Floor Lobby Roof Column


INFRARED IMAGES



Condition:

Pressurized

IR information	Value
Date of creation	17/03/2004
Time of creation	9:03:34 PM
Object parameter	Value
Ambient temperature	-3.0°C



Condition:

Depressurized

IR information	Value
Date of creation	17/03/2004
Time of creation	9:56:33 PM
Object parameter	Value
Ambient temperature	-3.0°C

Notes:
 Infrared images of precast nosing at the 2nd floor lobby roof. North-West corner of building.
 Building pressurized with building intake fans. Exhaust fans off.

 Heat loss noted during pressurized state only.
 Suspect air leakage at location.