


<b>Tag Number</b>	<b>DATE</b>
<b>9</b>	<b>Sept. 14/04</b>
<b>Leaking Component:</b>	<b>Inlet Fitting</b>
<b>Plant Column Reference:</b>	<b>C-9</b>
<b>Exact Leak Location: The fitting in the air inlet of the filter/ oiler unit is leaking. At Rapid Air machine # 938.</b>	


**Leak Location Photo: at arrow**



<b>Repair Record</b>	
Repair completed:	Yes ___ No ___
Repair Date:	<input type="text"/>
Repaired By:	<input type="text"/>
Notes:	<input type="text"/>

<b>Tag Number</b>	<b>DATE</b>
<b>10</b>	<b>Sept. 14/04</b>
<b>Leaking Component:</b>	<b>Hose Fitting</b>
<b>Plant Column Reference:</b>	<b>C-9</b>
<b>Exact Leak Location: The white supply hose connection to the oiler/ filter inlet is leaking. At Rapid air machine asset # 793.</b>	

**Leak Location Photo: at arrow**



<b>Repair Record</b>	
Repair completed:	Yes ___ No ___
Repair Date:	<input type="text"/>
Repaired By:	<input type="text"/>
Notes:	<input type="text"/>