


DESCRIPTION	DATE
200 HP Motor	Dec. 21/04

Identification: Dust Collector # 5

INFRARED IMAGE



PHOTO



IR information	Value
Date of creation	21/12/2004
Object parameter	Value
Ambient temperature	19.0°C
Label	Value
AR01 : max	58.2°C

Current Measured at Time of Inspection

Motor current: 56 A, 57 A, 57 A

Repair Notes

Repaired? Yes ___ No ___

Repaired date: _____

Notes:

INFORMATION:

Infrared image of the dust collector # 5 drive motor.

Located in the dust collector building.

Heating noted at the rear (outboard) bearing (at arrow in photo).

See IR information chart above for maximum temperature noted inside area box.

PRIORITY:

High

Medium

Low

ANOMALY:

Heating rear bearing