


FACILITY	DATE
Sample House: Interior	Jan. 18/05

Location: Basement, Cable Penetration

INFRARED IMAGE



PHOTO



IR information	Value
Date of creation	18/01/2005
Time of creation	7:09:08 PM
Object parameter	Value
Ambient temperature	23.0°C
Label	Value
AR01 : min	-5.5°C

INFORMATION:

Infrared image of the cable penetration on the south wall in the basement.
Cold section noted, at arrow in photo.

Suspect: cold air ingress at location.
Inspect further to verify cause.

See IR information chart above for minimum temperature inside area box.